


₽ PL-259-G Connector

 Slide coupling ring onto the cable orientation shown, then strip outer jacket by 1".



- 2. Carefully strip the coax to the dimensions shown.
- 3. Gently twist center wire to bind loose strands and carefully apply a very **thin, even** coat of solder to it.
- Thread the connector body onto the cable's outer jacket. Solder the tip, then solder the braid to the connector body through the body's four small holes. Be careful not to overheat the center wire.
- Trim any excess center wire. Screw the coupling ring on tightly.



Manufactured for Shakespeare Company, LLC, Columbia, SC 29223 www.shakespeareco.com ©2022 and TM Shakespeare Company, LLC. All rights reserved Made in China

shakespeare-marine.com

